

NO.	REGISTRY	OCCURENCE INFORMATION			DOCUMENTATION REFERENCE			ANOMALIES REPORTED	CORRECTIVE ACTION	COMPONENT		SYSTEM AND/OR COMPONENTS (OUT)			SYSTEM AND/OR COMPONENTS (IN)		
		DATE	FH	LDGS	TECH-LOG	WORK ORDER	TYPE			ATA	CRITICAL	DESCRIPTION	PART NUMBER	SERIAL NUMBER	DESCRIPTION	PART NUMBER	SERIAL NUMBER
01	CS-HGH	11-ago-08	73:30	260	-	20080500	MAREP	DISPLAY UNIT MALFUNCTION	DISPLAY UNIT REPLACED	31	NO	DISPLAY UNIT	7023460-804	06022721	DISPLAY UNIT	7023460-804	05092319
02	CS-HGH	11-ago-08	73:30	260	-	20080500	MAREP	LH MAIN WHEEL TYRE WITH HARD WEAR	LH MAIN WHEEL TYRE REPLACED	32	NO	LH MAIN WHEEL TYRE	DR9841T	UNK	LH MAIN WHEEL TYRE	DR9841T	08060317
03	CS-HGH	27-set-08	86:35	276	-	20080571	MAREP	CRACK/SUPERFICIAL DAMAGE ON TR BLADE FORK	REPAIRED IAW AGUSTAWESTLAND INSTRUCTIONS (REF. PSEA)	64	YES	-	-	-	-	-	-
04	CS-HGH	7-out-08	89:25	266	-	20080604	MAREP	TAIL ROTOR BLADE REMOVED FOR REPAIR	TAIL ROTOR BLADE REPAIRED AND REFITTED	64	YES	TAIL ROTOR BLADE	3G6410A00131	P649	TAIL ROTOR BLADE	3G6410A00131	P649
05	CS-HGH	21-out-08	108:55	407	0022/08	20080649	MAREP	DURING DAILY INSPECTION FOUND A MALFUNCTION ON DIM	PFD PILOT REPLACED	31	NO	DISPLAY UNIT	7023460-804	05092319	DISPLAY UNIT	7023460-804	05031884
06	CS-HGH	23-out-08	114:20	434	0025/08	20080663	MAREP	DURING DAILY INSPECTION FOUND OUT LEAKAGE FROM MGB	O-RING REPLACED	63	NO	O-RING	M83248/1-010	-	O-RING	M83248/1-010	-
07	CS-HGH	28-nov-08	136:06	492	-	20080730	MAREP	ENGINE SENSING ELEMENT: FIRE DETECTOR Nº2 FAILED	SENSING ELEMENT REPLACED	26	NO	FIRE DETECTOR SENSOR	636013450/170C10M	201183	FIRE DETECTOR SENSOR	636013450/170C10M	201582
08	CS-HGH	28-nov-08	136:06	492	-	20080730	MAREP	NIL	IGB OIL TEMPERATURE SENSOR REPLACED	63	NO	IGB OIL TEMPERATURE SE	3G6340V00651	UNK	IGB OIL TEMPERATURE SE	3G6340V00651	00861
09	CS-HGH	28-nov-08	136:06	492	-	20080730	MAREP	DISPLAY UNIT (CO-PILOT) MALFUNCTION	DISPLAY UNIT REPLACED	31	NO	DISPLAY UNIT	7023460-804	05031884	DISPLAY UNIT	7023460-804	07014331
10	CS-HGH	4-jan-09	147:30	569	0001/09	-	PIREP	DEFECT FOUND IN PRE-FLIGHT: FLASH LIGHTS MISSING	HEEL SYSTEM INOP. TRANSFERRED TO SECTION 4. MEL 33.6 C	33	NO	-	-	-	-	-	-
11	CS-HGH	6-jan-09	150:40	571	0002/09	20090006	PIREP	DEFECT FOUND IN PRE-FLIGHT: FLASH LIGHTS MISSING	REPAIRED WIRE CONECTION. TESTED OK.	33	NO	-	-	-	-	-	-
12	CS-HGH	23-jan-09	159:00	602	-	20090041	MAREP	TCAS ANTENNA FAIL	REPLACED THE ANTENNA CONNECTOR	34	NO	TNC BULKHEAD JACK	190321	-	TNC BULKHEAD JACK	190321	-
13	CS-HGH	27-jan-09	160:15	603	-	20090040	MAREP	MAIN ROTOR BLADE SUPERFICIAL CRACK	MAIN ROTOR BLADE REMOVED, REPAIRED AND REFITTED.	62	YES	MAIN ROTOR BLADE	3G6210A00131	P760	MAIN ROTOR BLADE	3G6210A00131	P760
14	CS-HGH	9-fev-09	181:10	651	0014/09	-	PIREP	MGB OIL FILTER LIGHT ON	CHECKED AND CLEANED THE POP-OUT	63	NO	-	-	-	-	-	-
15	CS-HGH	7-mai-09	184:35	655	0018/09	20090309	MAREP	ROD END WITH EXCESSIVE PLAY	ROD END ASSY REPLACED	55	YES	ROD END ASSY	3G5510A03931	182	ROD END ASSY	3G5510A03931	969
16	CS-HGH	7-mai-09	184:35	655	0018/09	-	MAREP	NIL	MGB OIL FILTER REPLACED	63	NO	MGB OIL FILTER ELEMENT	3G6320V04453	-	MGB OIL FILTER ELEMENT	3G6320V04453	-
17	CS-HGH	2-jul-09	187:00	659	0019/09	20090422	PIREP	FUEL PROBE #1 (NO FUEL INDICATION)	SECONDARY FUEL PROBE #1 REPLACED	28	NO	SECONDARY FUEL PROBE	3G2840V01051	372	SECONDARY FUEL PROBE	3G2840V01051	762
18	CS-HGH	2-jul-09	187:00	659	0019/09	20090422	PIREP	FMS #1 UNSERVICEABLE	ANOMALY NOT CONFIRMED	34	NO	-	-	-	-	-	-
19	CS-HGH	1-set-09	209:20	683	-	20090678	MAREP	SHOCK ABSORBER ON RH MAIN LANDING GEAR	SHOCK ABSORBER REPLACED	32	NO	MAIN SHOCK ABSORBER	3G3210V00331	00421	MAIN SHOCK ABSORBER	3G3210V00332	00815
20	CS-HGH	3-set-09	209:20	683	-	20090733	MAREP	NIL	TAIL POSITION LAMP REPLACED	33	NO	TAIL POSITION LAMP	6363/12-2	-	TAIL POSITION LAMP	6363/12-2	-
21	CS-HGH	14-set-09	209:20	683	0030/09	20090683	MAREP	MGB OIL FILTER: SNAG	MGB OIL FILTER REPLACED	63	NO	MGB OIL FILTER ELEMENT	3G6320V04453	-	MGB OIL FILTER ELEMENT	3G6320V04453	-
22	CS-HGH	16-out-09	213:45	687	0033/09	20090894	PIREP	HYDRAULIC 2 FILTER CLOGGED	VERIFIED LEVEL AND RESET POP OUT	29	NO	-	-	-	-	-	-
23	CS-HGH	15-dez-09	213:45	687	-	20091035	MAREP	EXHAUST WITH CRACKS IN INSULATION BLANKETS BEYOND LI	REPLACED EXHAUST	78	NO	NUMBER 1 NOZZLE	3G7800L00132	078	NUMBER 1 NOZZLE	3G7800L00132	HTF-003E1
24	CS-HGH	15-dez-09	213:45	687	-	20090135	MAREP	EXHAUST WITH CRACKS IN INSULATION BLANKETS BEYOND LI	REPLACED EXHAUST	78	NO	NUMBER 2 NOZZLE	3G7800L00232	078	NUMBER 2 NOZZLE	3G7800L00232	HTF-001E1
25	CS-HGH	15-dez-09	213:45	687	-	20090135	MAREP	NIL	REPLACED COVER DUE TO INCOMPATIBILITY WITH REPLACEM	78	NO	NUMBER 1 NOZZLE COVER	3G7800L00431	078	NUMBER 1 NOZZLE COVER	3G7800L00431	078
26	CS-HGH	15-dez-09	213:45	687	-	20090135	MAREP	NIL	REPLACED COVER DUE TO INCOMPATIBILITY WITH REPLACEM	78	NO	NUMBER 2 NOZZLE COVER	3G7800L00531	078	NUMBER 2 NOZZLE COVER	3G7800L00531	078
27	CS-HGH	13-jan-10	213:45	687	-	20090851	MAREP	RH AFTER COWLING WITH CRACKS	RH AFTER COWLING REPLACED	71	NO	RH AFT COWLING	3P7116A00132	-	RH AFT COWLING	3P7116A00132	-
28	CS-HGH	18-jan-10	215:20	685	0002/10	-	PIREP	FUEL PROBE #1 FAIL	VERIFIED THE CIRCUIT, FOUND OUT SOME WATER ON TB283,	28	NO	-	-	-	-	-	-
29	CS-HGH	20-jan-10	219:40	712	0004/10	20100057	PIREP	#1 SECONDARY FUEL PROBE INOP	#1 SECONDARY FUEL PROBE REPLACED	28	NO	SECONDARY FUEL PROBE	3G2840V01051	762	SECONDARY FUEL PROBE	3G2840V01051	437
30	CS-HGH	26-jan-10	222:15	732	-	20100079	MAREP	FUEL PROBE #1: SNAG	#1 SECONDARY FUEL PROBE REPLACED	28	NO	SECONDARY FUEL PROBE	3G2840V01051	437	SECONDARY FUEL PROBE	3G2840V01051	512
31	CS-HGH	26-jan-10	222:15	732	-	20100082	MAREP	YAW TRIM ACTUATOR: SNAG	YAW TRIM ACTUATOR REPLACED	67	NO	TRIM ACTUATOR ASSY	3G2220V00136	979	TRIM ACTUATOR ASSY	3G2220V00136	1642
32	CS-HGH	25-mar-10	225:52	759	-	20100083	MAREP	#1 VDR MODULE: SNAG	#1 VDR MODULE REPLACED	23	NO	VRD MODULE #1	7026201-801	07053330	VRD MODULE #1	7026201-801	07012912
33	CS-HGH	9-mar-10	225:52	759	-	20100193	MAREP	ANTENNA VHF #1 FOUND INOP	ANTENNA VHF #1 REPLACED	23	NO	ANTENNA VHF #1	VF10-210	8383	ANTENNA VHF #1	VF10-210	8883
34	CS-HGH	3-mar-10	225:20	758	0009/10	-	PIREP	FCU & FUEL PROBE FAIL WAS ON ALL TIME	CONNECTIONS TESTED. REFUEL CARRIED OUT.	28	NO	-	-	-	-	-	-
35	CS-HGH	12-mar-10	225:52	759	-	20100280	MAREP	#1 VDR MODULE FOUND INOP	#1 VDR MODULE REPLACED	23	NO	VRD MODULE #1	7026201-801	07012912	VRD MODULE #1	7026201-801	07053328
36	CS-HGH	25-mar-10	225:52	759	0010/10	20100314	PIREP	FUEL PROBE AVIONIC FAULT	#2 FUEL PROBE P/N 3G2840V01051, S/N 553 REMOVED AND F	28	NO	SECONDARY FUEL PROBE	3G2840V01051	553	SECONDARY FUEL PROBE	3G2840V01051	553
37	CS-HGH	25-mar-10	225:52	759	-	20100302	PIREP	FUEL PROBE CAUTION MESSAGE ON MFD	#1 FUEL PROBE REMOVED, FOUND TO BE CONTAMINATED WI	28	NO	SECONDARY FUEL PROBE	3G2840V01051	512	SECONDARY FUEL PROBE	3G2840V01051	512
38	CS-HGH	25-mar-10	225:52	759	0011/10	20100259	PIREP	BLUE MAIN ROTOR DAMPER LEAKING FROM PISTON	BLUE MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	0928	MAIN ROTOR DAMPER	3G6220V01351	2371
39	CS-HGH	26-mar-10	226:40	761	0011/10	20100335	PIREP	FCU & FUEL PROBE FAIL ON AVIONIC FAULT AFTER 30 MINUTE	#1 SECONDARY FUEL PROBE REPLACED	28	NO	SECONDARY FUEL PROBE	3G2840V01051	512	SECONDARY FUEL PROBE	3G2840V01051	534
40	CS-HGH	26-mar-10	225:52	759	-	20100305	MAREP	RH WINGLET FOUND DAMAGED	RH WINGLET REPLACED	55	NO	RH WINGLET	3G5510A04931	A7/064	RH WINGLET	3G5510A04931	-
41	CS-HGH	31-mar-10	229:10	764	-	20100337	PIREP	WRONG FUEL INDICATION IN TANK #1	#1 SECONDARY FUEL PROBE REPLACED	28	NO	SECONDARY FUEL PROBE	3G2840V01051	534	SECONDARY FUEL PROBE	3G2840V01051	1106
42	CS-HGH	1-abr-10	229:10	764	0014/10	20100350	PIREP	LH MAIN WHEEL TYRE WORN TO LIMITS	LH MAIN WHEEL TYRE REPLACED	32	NO	LH MAIN WHEEL TYRE	DR9841T	08060317	LH MAIN WHEEL TYRE	DR9841T	08221255
43	CS-HGH	26-abr-10	229:10	764	0015/10	-	PIREP	AIR CONDITIONING SYSTEM INOP	DEFERRED TO SECTION 4	21	NO	-	-	-	-	-	-
44	CS-HGH	26-abr-10	229:10	764	0015/10	20100435	PIREP	EXCESSIVE WATER IN FUEL TO BE INVESTIGATED & REPETITIVE	AUX. TANK REMOVED, MAIN TANK #1 REMOVED, TANK FOAM	28	NO	FUEL FILTER	3059779-01	-	FUEL FILTER	3059779-01	-
45	CS-HGH	27-abr-10	229:10	764	0017/10	20100459	PIREP	AIR CONDITIONING SYSTEM INOP (SECTION 4)	TASK 21-03 AIR CONDITIONING SERVICING COMPLIED	21	NO	-	-	-	-	-	-
46	CS-HGH	18-mai-10	233:45	774	0019/10	-	PIREP	CO-PILOT STOP WATCH INOP	VERIFIED AND REQUESTED INTERNAL BATTERY. TESTED. PASS.	31	NO	-	-	-	-	-	-
47	CS-HGH	31-mai-10	240:45	797	0024/10	20100608	PIREP	#2 SERVO LIGHT ON	#2 PRESSURE SWITCH REPLACED	67	NO	PRESSURE SWITCH	70797-85	2277	PRESSURE SWITCH	70797-85	3168
48	CS-HGH	22-jun-10	241:15	798	0026/10	-	PIREP	4 PAX SEAT HARNESSES REMOVED	ONLY 11 SEATS FITTED. ACCEPTABLE FOR FLIGHT.	25	NO	-	-	-	-	-	-
49	CS-HGH	22-jun-10	242:35	806	0027/10	-	PIREP	PAP FAILURE	RESET AIOP MODULE. TESTED SYSTEM ON GROUND. PASSED.	22	NO	-	-	-	-	-	-
50	CS-HGH	22-jun-10	242:35	806	0027/10	-	PIREP	WEATHER RADAR FAIL	PERFORMED OPERATIONAL TEST. OK.	34	NO	-	-	-	-	-	-
51	CS-HGH	23-jun-10	243:00	807	0028/10	20100695	PIREP	SERVO #2 ON	#2 HYD. SYSTEM PRESSURE SWITCH REPLACED	67	NO	PRESSURE SWITCH	70797-85	2329	PRESSURE SWITCH	70797-85	3219
52	CS-HGH	23-jun-10	243:00	807	0028/10	20100695	PIREP	BRIGHT PFD #1 (TOO BRIGHT)	#1 PFD REPLACED	31	NO	DISPLAY UNIT	7023460-804	06123846	DISPLAY UNIT	7023460-804	03100774
53	CS-HGH	13-ago-10	244:15	812	0031/10	20100846	PIREP	VIBRATION OUT OF LIMIT	MAIN ROTOR BLADE BLACK REPLACED DUE TO SERVICE CONV	62	YES	MAIN ROTOR BLADE	3G6210A00131	P756	MAIN ROTOR BLADE	3G6210A00131	N365
54	CS-HGH	9-set-10	244:15	812	-	20101022	MAREP	AFT LH FLOAT ASSY FAILED INFLATION CHECK (WO 20100995)	AFT LH FLOAT ASSY REPLACED	95	NO	AFT LH FLOAT ASSY	3G9560V00331	048	AFT LH FLOAT ASSY	3G9560V00332	011

NO.	REGISTRY	OCCURENCE INFORMATION			DOCUMENTATION REFERENCE			ANOMALIES REPORTED	CORRECTIVE ACTION	COMPONENT		SYSTEM AND/OR COMPONENTS (OUT)			SYSTEM AND/OR COMPONENTS (IN)		
		DATE	FH	LDGS	TECH-LOG	WORK ORDER	TYPE			ATA	CRITICAL	DESCRIPTION	PART NUMBER	SERIAL NUMBER	DESCRIPTION	PART NUMBER	SERIAL NUMBER
55	CS-HGH	13-set-10	244:15	812	0032/10	20101039	PIREP	VIBRATION OUT OF LIMIT & MAIN ROTOR BLADE DAMAGE FO	MAIN ROTOR BLADE BLUE REPLACED DUE TO SERVICE CONVE	62	YES	MAIN ROTOR BLADE	3G6210A00131	Q1061	MAIN ROTOR BLADE	3G6210A00131	N324
56	CS-HGH	16-set-10	245:15	819	0033/10	20101045	PIREP	RED MAIN ROTOR DAMPER LEAKING	RED MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	0922	MAIN ROTOR DAMPER	3G6220V01351	1045B
57	CS-HGH	7-out-10	245:15	819	0034/10	20101125	MAREP	BLACK MAIN ROTOR DAMPER PISTON BEARING CERAMIC COA	BLACK MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	0929	MAIN ROTOR DAMPER	3G6220V01351	1484B
58	CS-HGH	11-out-10	246:20	826	0035/10	-	PIREP	VIBRATION OUT OF LIMIT	WHITE TRACK ROD SHORTEN, WHITE TAB UP 2º, RED TAB UP 3	62	NO	-	-	-	-	-	-
59	CS-HGH	2-nov-10	255:05	844	0039/10	20101223	PIREP	#2 FUEL PROBE FAIL	#2 FUEL PROBE REMOVED, CLEANED, TESTED AND REFITTED.	28	NO	-	-	-	-	-	-
60	CS-HGH	2-nov-10	255:05	844	0039/10	20101223	PIREP	NOSE WHEEL SHOCK ABSORBER WITH LOW PRESSURE	NOSE WHEEL SHOCK ABSORBER PRESSURE CHECKED AND PRE	32	NO	-	-	-	-	-	-
61	CS-HGH	12-nov-10	255:05	844	0040/10	20101274	MAREP	3DU DEGRADE CAPTION ON CAS	REPLACED D.U. Nº3	31	NO	DISPLAY UNIT	7037620-814	07014331	DISPLAY UNIT	7037620-814	1009A146
62	CS-HGH	21-jan-11	255:05	844	0002/11	20101471	MAREP	FUEL PROBE #2 CAPTION ON CAS	#2 SECONDARY FUEL PROBE REPLACED	28	NO	SECONDARY FUEL PROBE	3G2840V01051	553	SECONDARY FUEL PROBE	3G2840V01051	1365
63	CS-HGH	26-jan-11	255:35	845	0003/11	20110064	PIREP	NOSE WHEEL GREEN LIGHT INOP	LANDING GEAR CONTROL PANEL REPLACED	32	NO	LANDING GEAR CONTROL	3G3230V00633	507304952	LANDING GEAR CONTROL	3G3230V00633	507368735
64	CS-HGH	26-jan-11	255:35	845	0003/11	20110064	MAREP	CABIN FIRE EXTINGUISHER FOUND UNDERWEIGHT	CABIN FIRE EXTINGUISHER REPLACED	26	NO	CABIN FIRE EXTINGUISHER	A072A02	05089	CABIN FIRE EXTINGUISHER	A072A02	06636
65	CS-HGH	26-jan-11	255:35	845	0003/11	20110064	MAREP	ORANGE MAIN ROTOR BLADE BONDING CONTACTOR FINGERS	BONDING CONTACTOR REPLACED	62	NO	CONTACTOR	3G6220A06633	-	CONTACTOR	3G6220A06633	-
66	CS-HGH	4-mar-11	260:25	863	0004/11	20101151	MAREP	LH CREW DOOR WINDOW SEAL TORN	LH CREW DOOR WINDOW SEAL REPLACED	56	NO	EXTRUDED, RUBBER, SEAL	999-1700-48-101G	-	EXTRUDED, RUBBER, SEAL	999-1700-48-101G	-
67	CS-HGH	31-mar-11	282:45	904	0012/11	20110374	MAREP	HUMS INDICATES MINOR CORRECTION ON TAIL ROTOR PITCH	RED & YELLOW PITCH LINKS ADJUSTED	64	YES	-	-	-	-	-	-
68	CS-HGH	15-jun-11	286:30	930	-	20110637	MAREP	PUNCTURE DAMAGE TO TAIL FIN INNER SKIN LH SIDE BEHIND	REPAIR CARRIED OUT IAW TMI 139-211	55	NO	-	-	-	-	-	-
69	CS-HGH	15-jun-11	286:30	930	-	20110637	MAREP	ORANGE MAIN ROTOR LAG DAMPER LEAKING BEYOND LIMITS	ORANGE MAIN ROTOR LAG DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	0924	MAIN ROTOR DAMPER	3G6220V01351	2167
70	CS-HGH	15-jun-11	286:30	930	-	20110637	MAREP	WHITE MAIN ROTOR LAG DAMPER LEAKING BEYOND LIMITS	WHITE MAIN ROTOR LAG DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	0923	MAIN ROTOR DAMPER	3G6220V01351	0376
71	CS-HGH	7-jul-11	302:20	902	0010/11	20110737	MAREP	RH MAIN WHEEL TIRE WORN TO LIMITS	RH MAIN WHEEL TIRE REPLACED	32	NO	MAIN WHEEL ASSY	3G3240V00231	MAR07-00445	MAIN WHEEL ASSY	3G3240V00231	08221382
72	CS-HGH	3-ago-11	303:50	940	0011/11	-	PIREP	HYDRAULIC FILTER #2 SHOWS BLOCKED ON SYNOPTIC PAGE	FILTER ELEMENTS REPLACED (QTY.2)	29	NO	PCM FILTER ELEMENT	1865-36	-	PCM FILTER ELEMENT	1865-36	-
73	CS-HGH	12-ago-11	304:20	946	-	20110854	MAREP	NLG ASSY SHOCK ABSORBER COLLAPSED	NOSE LANDING GEAR ASSY REPLACED	32	YES	NOSE LANDING GEAR ASSY	3G3220V00135	00258	NOSE LANDING GEAR ASSY	3G3220V00135	00174
74	CS-HGH	16-ago-11	316:45	947	0015/11	-	PIREP	RADAR UNSERVICEABLE, WITH 105% PI, LEFT RADAR IS IN FULL	AIR TEST CARRIED OUT WITH A/C LOADED. RADAR CONNECTO	34	NO	-	-	-	-	-	-
75	CS-HGH	25-ago-11	322:15	963	0021/11	-	MAREP	RADAR UNSERVICEABLE	RADAR ANTENNA REPLACED	34	NO	WEATHER RADAR ANTENNA	7021450-601	07057508	WEATHER RADAR ANTENNA	7021450-601	08028242
76	CS-HGH	27-ago-11	322:15	963	-	20110932	MAREP	MAIN ROTOR DAMPER LEAKING FROM PISTON	MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	2371	MAIN ROTOR DAMPER	3G6220V01351	1918B
77	CS-HGH	11-out-11	327:15	976	0024/11	-	MAREP	BEARING LOOSEN BELLCRANK	YAW Y9/Y10 BELLCRANK REPLACED	67	YES	LEVER ASSY	3E6722A01236	213	LEVER ASSY	3E6722A01236	44
78	CS-HGH	7-nov-11	351:40	1049	0038/11	20111202	PIREP	ROTOR BRAKE BOTH LIGHTS BLINKS	REPLACED ROTOR BRAKE ACTUATION ASSY	63	NO	ROTOR BRAKE ACTUATOR	3G6352V02451	254	ROTOR BRAKE ACTUATOR	3G6352V02451	333
79	CS-HGH	23-nov-11	374:10	1104	0048/11	20111273	MAREP	MAIN ROTOR DAMPER WITH EXCESSIVE LEAK	MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01352	1045B	MAIN ROTOR DAMPER	3G6220V01352	0364
80	CS-HGH	31-jan-12	389:50	1143	0013/12	-	MAREP	NIL	LH MAIN WHEEL TYRE REPLACED	32	NO	LH MAIN WHEEL TYRE	DR9841T	08254130	LH MAIN WHEEL TYRE	DR9841T	08221225
81	CS-HGH	21-mar-12	407:50	1158	-	20120224	MAREP	CABIN ASSY STA 5795 WL 2470 FOUND CRACKED	REPAIR IAW ASRP DMC 39-A-53-30-01-00A-664A-A (MAIN CABE	53	NO	-	-	-	-	-	-
82	CS-HGH	9-abr-12	431:50	1177	0030/12	-	PIREP	FWD SERVO #2 LIGHT ON	FWD SERVO #2 PRESSURE SWITCH REPLACED	67	NO	PRESSURE SWITCH	70797-85	1225	PRESSURE SWITCH	70797-85	3206
83	CS-HGH	17-abr-12	446:20	1229	0038/12	-	MAREP	POWER CONTROL MODULE FILTER #2 (FILTER CAPTION)	PCM FILTER #2 REPLACED	29	NO	PCM FILTER ELEMENT	1865-36	-	PCM FILTER ELEMENT	1865-36	-
84	CS-HGH	18-abr-12	448:10	1233	0039/12	-	MAREP	NIL	RH BAGGAGE RAM DOOR STRUT REPLACED	52	NO	GAS SPRING	A441A0500B19B060	-	GAS SPRING	A441A0500B19B060	-
85	CS-HGH	19-abr-12	449:55	1238	0040/12	20120472	MAREP	NIL	CRACK REPAIRED ON VIBRATION ABSORBER ZONE	53	NO	-	-	-	-	-	-
86	CS-HGH	29-mai-12	496:45	1359	0066/12	-	MAREP	NIL	TAIL POSITION LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
87	CS-HGH	13-jun-12	516:00	1409	0076/12	-	PIREP	ROTOR BRAKE INOP & "ROTOR BRK FAIL" ON CAS MESSAGE	TRANSFERRED TO SECTION 4. NIL SPARES AVAILABLE. AGUSTA	63	NO	-	-	-	-	-	-
88	CS-HGH	15-jun-12	517:40	1413	0077/12	-	MAREP	NIL	RH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
89	CS-HGH	19-jun-12	521:50	1421	0079/12	-	MAREP	NIL	RED TAIL ROTOR DAMPER ROD END ASSY REPLACED	64	YES	ROD END ASSY	Y42286-31-1	0967	ROD END ASSY	Y42286-31-1	5520
90	CS-HGH	19-jun-12	521:50	1421	0079/12	-	MAREP	NIL	BLUE TAIL ROTOR DAMPER ROD END ASSY REPLACED	64	YES	ROD END ASSY	Y42286-31-1	0975	ROD END ASSY	Y42286-31-1	5468
91	CS-HGH	20-jun-12	523:40	1425	0080/12	-	MAREP	NIL	LH SLIDING DOOR STOP SPRING REPLACED	52	NO	STOP SPRING	3G5212A04152	-	STOP SPRING	3G5212A04152	-
92	CS-HGH	20-jun-12	523:40	1425	0080/12	-	MAREP	NIL	RH WINDSCREEN WIPER BLADE REPLACED	30	NO	RH WIPER BLADE	204-070-907-11	-	RH WIPER BLADE	204-070-907-11	-
93	CS-HGH	19-jul-12	566:35	1548	0106/12	-	MAREP	NIL	WHITE TAIL ROTOR DAMPER ROD END ASSY REPLACED	64	YES	ROD END ASSY	Y42286-31-1	0961	ROD END ASSY	Y42286-31-1	6541
94	CS-HGH	19-jul-12	566:35	1548	0106/12	-	MAREP	NIL	YELLOW TAIL ROTOR DAMPER ROD END ASSY REPLACED	64	YES	ROD END ASSY	Y42286-31-1	0956	ROD END ASSY	Y42286-31-1	6531
95	CS-HGH	1-ago-12	581:50	1585	0114/12	-	PIREP	FLIGHT ABORTED ON GROUND RUN. ENGINE #1 CONTROL LEV	ENG. #1 POWER CONTROL CABLE REPLACED	76	NO	POWER CONTROL CABLE	3G7610V00532	0265	POWER CONTROL CABLE	3G7610V00532	57841-14
96	CS-HGH	3-ago-12	582:15	1587	0115/12	20120896	MAREP	PITCH LINKS FOUND OUT OF LIMITS	TR PITCH LINKS REPLACED	62	YES	PITCH LINK	3G6230A01032	735	PITCH LINK	3G6230A01033	MCR1120
97	CS-HGH	3-ago-12	582:15	1587	0115/12	20120896	MAREP	PITCH LINKS FOUND OUT OF LIMITS	TR PITCH LINKS REPLACED	62	YES	PITCH LINK	3G6230A01032	736	PITCH LINK	3G6230A01033	1171R
98	CS-HGH	3-ago-12	582:15	1587	0115/12	20120896	MAREP	PITCH LINKS FOUND OUT OF LIMITS	TR PITCH LINKS REPLACED	62	YES	PITCH LINK	3G6230A01032	737	PITCH LINK	3G6230A01033	656R
99	CS-HGH	3-ago-12	582:15	1587	0115/12	20120896	MAREP	PITCH LINKS FOUND OUT OF LIMITS	TR PITCH LINKS REPLACED	62	YES	PITCH LINK	3G6230A01032	738	PITCH LINK	3G6230A01033	881R
100	CS-HGH	3-ago-12	582:15	1587	0115/12	20120896	MAREP	PITCH LINKS FOUND OUT OF LIMITS	TR PITCH LINKS REPLACED	62	YES	PITCH LINK	3G6230A01032	739	PITCH LINK	3G6230A01033	1236R
101	CS-HGH	16-ago-12	594:55	1620	0123/12	-	MAREP	NIL	TGB FAIRING SUPPORT ASSY REPLACED	53	NO	FAIRING SUPPORT ASSY	3G5355A05031	-	FAIRING SUPPORT ASSY	3G5355A05031	-
102	CS-HGH	26-ago-12	598:25	1628	0127/12	-	MAREP	NIL	WHITE LAG DAMPER ASSY REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	0376	MAIN ROTOR DAMPER	3G6220V01351	MCR6507
103	CS-HGH	26-ago-12	598:25	1628	-	20120972	MAREP	STARTER GENERATOR #2 BRUSHES WORN TO LIMITS	STARTER GENERATOR #2 BRUSHES REPLACED	24	NO	BRUSH SET	3005GL1009-5	-	BRUSH SET	3005GL1009-5	-
104	CS-HGH	26-ago-12	598:25	1628	-	20120972	MAREP	PAIR OF TAIL ROTOR CROSSHEAD SCISSOR BUSHINGS WORN	TAIL ROTOR CROSSHEAD SCISSOR BUSHINGS REPLACED	64	NO	SLEEVE BEARING	M81934/2-06C014	-	SLEEVE BEARING	M81934/2-06C014	-
105	CS-HGH	26-ago-12	598:25	1628	-	20120972	MAREP	PAIR OF TAIL ROTOR CROSSHEAD SCISSOR BUSHINGS WORN	TAIL ROTOR CROSSHEAD SCISSOR BUSHINGS REPLACED	64	NO	SLEEVE BEARING	M81934/2-06C014	-	SLEEVE BEARING	M81934/2-06C014	-
106	CS-HGH	26-ago-12	598:25	1628	-	20120972	MAREP	TAIL ROTOR CONTROL SLIDER BUSHING WORN	TAIL ROTOR CONTROL SLIDER BUSHING REPLACED	64	YES	SLIDER BUSHING	3G6430L00251	UNK	SLIDER BUSHING	3G6430L00251	11X75378120023
107	CS-HGH	6-set-12	614:30	1668	0135/12	-	MAREP	TAIL SERVO ACTUATOR WITH LEAKAGE	TAIL SERVO ACTUATOR REPLACED	67	YES	TAIL ROTOR ACTUATOR	3G6730V00731	MSC209025	TAIL ROTOR ACTUATOR	3G6730V00731	MSC217164

NO.	REGISTRY	OCCURENCE INFORMATION			DOCUMENTATION REFERENCE			ANOMALIES REPORTED	CORRECTIVE ACTION	COMPONENT		SYSTEM AND/OR COMPONENTS (OUT)			SYSTEM AND/OR COMPONENTS (IN)		
		DATE	FH	LDGS	TECH-LOG	WORK ORDER	TYPE			ATA	CRITICAL	DESCRIPTION	PART NUMBER	SERIAL NUMBER	DESCRIPTION	PART NUMBER	SERIAL NUMBER
108	CS-HGH	9-set-12	614:30	1668	-	20120783	MAREP	PIPE ASSY P/N 3G2920A04431 FOUND CHAFED	PIPE ASSY P/N 3G2920A04431 REPLACED	29	NO	TUBE ASSY	3G2920A04431	-	TUBE ASSY	3G2920A04431	-
109	CS-HGH	9-set-12	614:30	1668	-	20120783	MAREP	MAIN ROTOR LOWER SCISSORS WORN	MAIN ROTOR LOWER SCISSORS & BUSHINGS REPLACED	62	YES	BOTTOM ROTATING SCISSORS	3G6230A00932	P515	BOTTOM ROTATING SCISSORS	3G6230A00932	V994
110	CS-HGH	9-set-12	614:30	1668	-	20120783	MAREP	MAIN ROTOR LOWER SCISSORS WORN	MAIN ROTOR LOWER SCISSORS & BUSHINGS REPLACED	62	YES	BOTTOM ROTATING SCISSORS	3G6230A00932	P511	BOTTOM ROTATING SCISSORS	3G6230A00932	V1080
111	CS-HGH	9-set-12	614:30	1668	-	20120783	MAREP	MAIN ROTOR LOWER SCISSORS WORN	MAIN ROTOR LOWER SCISSORS & BUSHINGS REPLACED	62	YES	BUSHING	3G6230A01852	P522	BUSHING	3G6230A01852	P720
112	CS-HGH	24-out-12	695:35	1869	0176/12	20120748	MAREP	ROTOR BRAKE STUCK IN RETRACTED POSITION	ROTOR BRAKE ACTUATOR REPLACED (SECTION 4)	63	NO	ROTOR BRAKE	3G6352V02451	333	ROTOR BRAKE	3G6352V02452	2089
113	CS-HGH	25-out-12	696:25	1871	0177/12	-	MAREP	NIL	AUTOMATIC PILOT #2 CAPTION LAMP REPLACED	22	NO	CAPTION LAMP	6839	-	CAPTION LAMP	6839	-
114	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	SCISSORS BUSHING	3G6230V00751	502	SCISSORS BUSHING	3G6230V00751	12218
115	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	SCISSORS BUSHING	3G6230V00751	513	SCISSORS BUSHING	3G6230V00751	12219
116	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	SCISSORS BUSHING	3G6230V00751	489	SCISSORS BUSHING	3G6230V00751	12220
117	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	SCISSORS BUSHING	3G6230V00751	493	SCISSORS BUSHING	3G6230V00751	12213
118	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	TOP ROTATING SCISSORS	3G6230A00832	495	TOP ROTATING SCISSORS	3G6230A00832	12216
119	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	TOP ROTATING SCISSORS	3G6230A00832	494	TOP ROTATING SCISSORS	3G6230A00832	12214
120	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	TOP ROTATING SCISSORS	3G6230A00832	487	TOP ROTATING SCISSORS	3G6230A00832	12215
121	CS-HGH	26-out-12	700:35	1879	0179/12	-	MAREP	NIL	MAIN ROTOR UPPER SCISSORS BUSHINGS REPLACED	62	YES	TOP ROTATING SCISSORS	3G6230A00832	496	TOP ROTATING SCISSORS	3G6230A00832	12218
122	CS-HGH	30-out-12	704:55	1889	0182/12	-	PIREP	BLACK MAIN ROTOR DAMPER - OIL LEAK	BLACK MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	2167	MAIN ROTOR DAMPER	3G6220V01352	0668
123	CS-HGH	30-out-12	704:55	1889	0182/12	-	PIREP	NIL	YELLOW MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	1484B	MAIN ROTOR DAMPER	3G6220V01352	MCR6662
124	CS-HGH	30-out-12	704:55	1889	0182/12	-	PIREP	NIL	LH LANDING LAMP REPLACED	33	NO	LANDING LAMP	GE4596	-	LANDING LAMP	GE4596	-
125	CS-HGH	15-nov-12	727:15	1951	0193/12	-	MAREP	NIL	WINDSHIELD WASHING/WIPING CONTROL PANEL REPLACED	30	NO	WINDSHIELD WIPING/WASHING	3G3040V00255	S07309594	WINDSHIELD WIPING/WASHING	3G3040V00255	S07309601
126	CS-HGH	19-nov-12	732:10	1962	0196/12	-	MAREP	NIL	BLUE TAIL ROTOR DAMPER REPLACED	64	YES	TAIL ROTOR DAMPER	3G6420V00455	LK1091	TAIL ROTOR DAMPER	3G6420V00455	LK1607
127	CS-HGH	1-dez-12	758:05	2025	0209/12	20121289	MAREP	LIGHTNING CONDUCTOR JUMPER RED BLADE (BROKEN)	LIGHTNING CONDUCTOR JUMPER RED BLADE REPLACED	64	NO	LIGHTNING CONDUCTOR	A537A03AA03-0265	-	LIGHTNING CONDUCTOR	A537A03AA03-0265	-
128	CS-HGH	1-dez-12	758:05	2025	0209/12	20121294	MAREP	LH BAGGAGE COMPARTMENT GAS SPRING (BROKEN)	LH BAGGAGE COMPARTMENT GAS SPRING REPLACED	52	NO	GAS SPRING	A441A0500819B060	-	GAS SPRING	A441A0500819B060	-
129	CS-HGH	1-dez-12	758:05	2025	-	20121289	MAREP	FOUND FREE PLAY ON ONE DAMPER (IXAIR REPORT)	YELLOW TAIL ROTOR DAMPER REPLACED DUE TO EXCESSIVE PLAY	64	YES	TAIL ROTOR DAMPER	3G6420V00455	LK1087	TAIL ROTOR DAMPER	3G6420V00455	LK3450
130	CS-HGH	3-dez-12	759:00	2027	0210/12	20121289	MAREP	NIL	TAIL POSITION LIGHT REPLACED	33	NO	POSITION LAMP	GE1683	-	POSITION LAMP	GE1683	-
131	CS-HGH	4-dez-12	767:10	2049	-	20121290	MAREP	FOUND HOLES ON PROTECTIVE SWASHPLATE (IXAIR REPORT)	SWASHPLATE BOOT REPAIRED	62	NO	-	-	-	-	-	-
132	CS-HGH	5-dez-12	763:30	2038	0212/12	-	PIREP	DISPLAY UNIT #2 INOP	RECYCLED CIRCUIT BREAKERS AND PERFORMED OPERATIONAL TEST	31	NO	-	-	-	-	-	-
133	CS-HGH	6-dez-12	767:10	2049	0214/12	-	MAREP	NIL	DISPLAY UNIT DU-1080-2 REPLACED DUE TO SERVICE CONVENIENCE	31	NO	DISPLAY UNIT	7037620-814	07013998	DISPLAY UNIT	7037620-814	07125463
134	CS-HGH	9-dez-12	770:50	2059	0217/12	20121291	MAREP	BAFFLE SEAL LH SIDE ON EXHAUST	REPOSITIONED FLAT SEAL ON THE NOZZLE 1	78	NO	-	-	-	-	-	-
135	CS-HGH	13-dez-12	782:05	2088	0223/12	-	MAREP	NIL	YELLOW TAIL ROTOR DAMPER REPLACED	64	YES	TAIL ROTOR DAMPER	3G6420V00455	LK1087	TAIL ROTOR DAMPER	3G6420V00455	LK3450
136	CS-HGH	24-dez-12	797:40	2120	-	20121288	MAREP	LIFE RAFT CONTAINER LH SIDE IN VERY BAD CONDITION	PAINT FINISH RESTORED	95	NO	-	-	-	-	-	-
137	CS-HGH	16-jan-13	856:25	2275	0009/13	20130150	PIREP	WHEN LANDING GEAR IS DOWN, THE RH GREEN LIGHT REMAINS ON	DEFECT DEFERRED TO SECTION 4. LANDING GEAR LOCKED DOWN	32	NO	CABLE LOOM ASSY	1653A0300-02	0824	CABLE LOOM ASSY	1653A0300-02	1614
138	CS-HGH	28-fev-13	894:20	2357	0045/13	-	MAREP	RH MAIN WHEEL TYRE FOUND DAMAGED	RH MAIN WHEEL TYRE REPLACED	32	NO	RH MAIN WHEEL TYRE	DR9841T	08221383	RH MAIN WHEEL TYRE	DR9841T	08221223
139	CS-HGH	15-mar-13	915:55	2425	0057/13	-	MAREP	POWER CONTROL MODULE FILTER (FILTER CAPTION)	PCM FILTER #2 REPLACED	29	NO	PCM FILTER ELEMENT	1865-36	-	PCM FILTER ELEMENT	1865-36	-
140	CS-HGH	17-mar-13	915:55	2425	-	20130201	MAREP	#1 STARTER GENERATOR BRUSHES FOUND WORN	#1 STARTER GENERATOR BRUSHES REPLACED	24	NO	BRUSH SET	3005GL1009-5	-	BRUSH SET	3005GL1009-5	-
141	CS-HGH	17-mar-13	915:55	2425	-	20130201	MAREP	BOTH EXHAUST NOZZLES REAR SEALS REQUIRE REPLACING	EXHAUST NOZZLES REAR FLAT SEALS REPLACED	78	NO	FLAT SEAL	3P7800A13751	-	FLAT SEAL	3P7800A13751	-
142	CS-HGH	17-mar-13	915:55	2425	-	20130201	MAREP	BOTH EXHAUST NOZZLES REAR SEALS REQUIRE REPLACING	EXHAUST NOZZLES REAR FLAT SEALS REPLACED	78	NO	FLAT SEAL	3P7800A13751	-	FLAT SEAL	3P7800A13751	-
143	CS-HGH	17-mar-13	915:55	2425	-	20130201	MAREP	ENGINE #1 P2.8 VALVE FOUND WORN	ENGINE #1 P2.8 VALVE REPLACED	72	NO	CHECK VALVE ASSY	3070081-01	-	CHECK VALVE ASSY	3074845-01	-
144	CS-HGH	15-abr-13	947:45	2504	0078/13	-	MAREP	REPLACED DUE TO BT 139-214 (WO 20110223)	STANDBY ATTITUDE INDICATOR	34	NO	STANDBY ATTITUDE INDICATOR	501-1860-0201	0206	STANDBY ATTITUDE INDICATOR	501-1860-0201	1445
145	CS-HGH	19-abr-13	955:15	2522	0082/13	-	PIREP	LEFT CABIN DOOR HARD TO CLOSE	ROLLER P/N 3G5213A02051 REPLACED & LUBRICATED MECHANISM	52	NO	ROLLER	3G5213A02051	-	ROLLER	3G5213A02051	-
146	CS-HGH	10-mai-13	984:50	2592	0096/13	-	MAREP	NIL	RH POSITION LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
147	CS-HGH	16-mai-13	993:25	2612	0100/13	20130438	MAREP	RED TAIL ROTOR DAMPER: BODY BEARING WORN TO LIMIT	RED TAIL ROTOR DAMPER REPLACED	64	YES	TAIL ROTOR DAMPER	3G6420V00455	LK1090	TAIL ROTOR DAMPER	3G6420V00455	LK1662
148	CS-HGH	16-mai-13	993:25	2612	0100/13	20130438	MAREP	WHITE TAIL ROTOR DAMPER: BODY BEARING WORN TO LIMIT	WHITE TAIL ROTOR DAMPER REPLACED	64	YES	TAIL ROTOR DAMPER	3G6420V00455	LK1089	TAIL ROTOR DAMPER	3G6420V00455	LK1861
149	CS-HGH	3-jun-13	1013:15	2670	0111/13	-	MAREP	NIL	MAIN ROTOR ORANGE OUTBOARD LIGHTNING CONDUCTOR REPLACED	62	NO	LIGHTNING CONDUCTOR	3G6220A07331	-	LIGHTNING CONDUCTOR	3G6220A07331	-
150	CS-HGH	10-jun-13	1022:35	2696	0116/13	-	MAREP	NIL	RH PILOT DOOR GAS SPRING REPLACED	52	NO	GAS SPRING	A441A0250W15W120	-	GAS SPRING	A441A0250W15W120	-
151	CS-HGH	17-jul-13	1070:45	2834	0143/13	-	MAREP	NIL	BLUE MAIN ROTOR DAMPER EYE END ASSY REPLACED	62	YES	ROD END ASSY	M006-01H004-045	MCR2246	ROD END ASSY	M006-01H004-045	MCR6680
152	CS-HGH	18-jul-13	1071:35	2836	0144/13	-	MAREP	NIL	RH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
153	CS-HGH	29-jul-13	1082:25	2863	0149/13	-	MAREP	NIL	TAIL POSITION LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
154	CS-HGH	6-ago-13	1090:30	2884	0154/13	-	MAREP	NIL	MAIN ROTOR RED DAMPER OUTBOARD BONDING CONDUCTOR REPLACED	62	NO	LIGHTNING CONDUCTOR	3G6220A07331	-	LIGHTNING CONDUCTOR	3G6220A07331	-
155	CS-HGH	12-ago-13	1095:35	2896	0157/13	-	MAREP	NIL	BLUE TAIL ROTOR BLADE LIGHTNING CONDUCTOR REPLACED	64	NO	LIGHTNING CONDUCTOR	A537A03AA03-0265	-	LIGHTNING CONDUCTOR	A537A03AA03-0265	-
156	CS-HGH	15-ago-13	1099:45	2907	0160/13	20130415	MAREP	PANEL ASSY AT STA 1070 WITH CRACK	STA 1070 PANEL REPAIRED	53	NO	-	-	-	-	-	-
157	CS-HGH	9-set-13	1127:00	2978	0175/13	-	MAREP	NIL	MAIN ROTOR WHITE OUTBOARD LIGHTNING CONDUCTOR REPLACED	62	NO	LIGHTNING CONDUCTOR	3G6220A07331	-	LIGHTNING CONDUCTOR	3G6220A07331	-
158	CS-HGH	30-set-13	1142:40	3014	0184/13	-	MAREP	NIL	WHITE MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01352	MCR6507	MAIN ROTOR DAMPER	3G6220V01352	2083
159	CS-HGH	2-out-13	1146:20	3024	0186/13	-	MAREP	NIL	RH POSITION LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
160	CS-HGH	15-out-13	1148:00	3028	0188/13	20130897	MAREP	FIRE DETECTION CAPTION	ENGINE #1 FIRE SENSOR REPLACED	26	NO	ENGINE FIRE SENSOR ELEMENT	6360-13-450/170C-10	201116	ENGINE FIRE SENSOR ELEMENT	6360-13-450/170C-10	203437

NO.	REGISTRY	OCCURENCE INFORMATION			DOCUMENTATION REFERENCE			ANOMALIES REPORTED	CORRECTIVE ACTION	COMPONENT		SYSTEM AND/OR COMPONENTS (OUT)			SYSTEM AND/OR COMPONENTS (IN)		
		DATE	FH	LDGS	TECH-LOG	WORK ORDER	TYPE			ATA	CRITICAL	DESCRIPTION	PART NUMBER	SERIAL NUMBER	DESCRIPTION	PART NUMBER	SERIAL NUMBER
161	CS-HGH	18-out-13	1152:35	3041	0191/13	-	MAREP	NIL	LH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
162	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	LH MAIN WHEEL TIRE WORN	LH MAIN WHEEL TIRE REPLACED	32	NO	LH MAIN WHEEL TYRE	DR9841T	08221225	LH MAIN WHEEL TYRE	DR9841T	08221251
163	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	TAIL PLANE RH ROD WITH PLAY BEYOND LIMITS	TAIL PLANE RH ROD REPLACED	55	YES	ROD END ASSY	3G5510A03931	UNK	ROD END ASSY	3G5510A03931	MCR4112
164	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	MR BOTTOM SCISSOR WORN BEYOND LIMITS	MR BOTTOM SCISSOR REPLACED	62	YES	BOTTOM ROTATING SCISS	3G6230A00932	V1080	BOTTOM ROTATING SCISS	3G6230A00932	V1527
165	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	RH LANDING LIGHT INOP	RH LANDING LIGHT REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
166	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	NIL	EMERGENCY BATTERIES ASSY REPLACED	24	NO	BATTERY HOLDER ASSY	2013-1A	97620	BATTERY HOLDER ASSY	2013-1A	120107
167	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	NIL	EMERGENCY BATTERIES ASSY REPLACED	24	NO	BATTERY HOLDER ASSY	2013-1A	97769	BATTERY HOLDER ASSY	2013-1A	120105
168	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	ENGINE #2 P2.8 VALVE FOUND WORN	ENGINE #2 P2.8 VALVE REPLACED	72	NO	CHECK VALVE ASSY	3070081-01	-	CHECK VALVE ASSY	3074845-01	-
169	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	FUEL NOZZLES ENGINE #1 TO SEND FOR INSPECTION	FUEL NOZZLES ENGINE #1 REPLACED	72	NO	FUEL NOZZLES	140976	-	FUEL NOZZLES	140976	-
170	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	FUEL NOZZLES ENGINE #2 TO SEND FOR INSPECTION	FUEL NOZZLES ENGINE #2 REPLACED	72	NO	FUEL NOZZLES	135793	-	FUEL NOZZLES	135793	-
171	CS-HGH	27-nov-13	1178:25	3148	-	20130866	MAREP	WINDSHIELD WASHING PUMP INOP	WINDSHIELD WASHING PUMP REPLACED	30	NO	PUMP	2320M-33-1	0037	PUMP	2320M-33-1	00385
172	CS-HGH	11-dez-13	1192:10	3182	0215/13	-	MAREP	MGB LH FREEWHEEL COVER OIL JET ASSY DAMAGED	MGB LH FREEWHEEL COVER OIL JET ASSY REPLACED	63	NO	OIL JET COVER	3K6320A03331	-	OIL JET COVER	3K6320A03331	-
173	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSORS ASSY	3G6430A00331	P670	SCISSORS ASSY	3G6430A00335	V24916
174	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSORS ASSY	3G6430A00331	P671	SCISSORS ASSY	3G6430A00335	V24918
175	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSORS ASSY	3G6430A00331	P668	SCISSORS ASSY	3G6430A00335	V24914
176	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSORS ASSY	3G6430A00331	P669	SCISSORS ASSY	3G6430A00335	V24915
177	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSOR COUPLING	3G6430A02353	N590	SCISSOR COUPLING	3G6430A02353	V1008
178	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSOR COUPLING	3G6430A02353	N591	SCISSOR COUPLING	3G6430A02353	V1009
179	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSOR COUPLING	3G6430A02353	N593	SCISSOR COUPLING	3G6430A02353	V1011
180	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SCISSOR COUPLING	3G6430A02353	N592	SCISSOR COUPLING	3G6430A02353	V1010
181	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SHORT COUPLING	3G6430A01455	N298	SHORT COUPLING	3G6430A01455	V778
182	CS-HGH	12-dez-13	1195:45	3191	0216/13	-	MAREP	TAIL ROTOR SCISSORS WORN; TAIL ROTOR HUB FLANGED BUS	TAIL ROTOR SCISSORS COMPONENTS REPLACED; TAIL ROTOR	64	YES	SHORT COUPLING	3G6430A01455	N296	SHORT COUPLING	3G6430A01455	V779
183	CS-HGH	16-dez-13	1195:55	3192	0217/13	-	MAREP	RH TOP MAINTENANCE STEP DAMAGED	FWD REST MAINT CABLE REPLACED	52	NO	WIRE ROPE ASSY	NAS313C20-0103	-	WIRE ROPE ASSY	NAS313C20-0103	-
184	CS-HGH	19-dez-13	1201:20	3205	0220/13	-	MAREP	NIL	RED MAIN ROTOR DAMPER ROUTER BOLTS SPECIAL WASHER	62	NO	WASHER	3G6220A05051	-	WASHER	3G6220A05051	-
185	CS-HGH	19-dez-13	1201:20	3205	0220/13	-	MAREP	NIL	WHITE MAIN ROTOR DAMPER ROUTER BOLTS SPECIAL WASHER	62	NO	WASHER	3G6220A05051	-	WASHER	3G6220A05051	-
186	CS-HGH	20-dez-13	1202:10	3208	0221/13	-	MAREP	NIL	BLACK MAIN ROTOR DAMPER OUTBOARD LIGHTNING CONDU	62	NO	LIGHTNING CONDUCTOR	3G6220A07331	-	LIGHTNING CONDUCTOR	3G6220A07331	-
187	CS-HGH	20-dez-13	1202:10	3208	0221/13	-	MAREP	NIL	BLUE & ORANGE MAIN ROTOR DAMPERS REFILLED	62	NO	-	-	-	-	-	-
188	CS-HGH	24-jan-14	1242:00	3331	0018/14	-	MAREP	NIL	AFCS CONTROL PANEL ATT LAMP REPLACED	22	NO	AP CONTROL PANEL LAMP	OL685-297	-	AP CONTROL PANEL LAMP	OL685-297	-
189	CS-HGH	10-fev-14	1260:30	3376	0027/14	-	MAREP	NIL	AIR CONDITIONING SYSTEM DUST (BETWEEN EVAPORATORS)	21	NO	FIRE BLANKET	3G2150V02051	-	FIRE BLANKET	3G2150V02051	-
190	CS-HGH	13-fev-14	1267:30	3394	0030/14	-	MAREP	CONTROL ROD ASSY WITH FIXED BEARING WORN	CONTROL ROD ASSY REPLACED DUE TO FIXED BEARING WORN	67	YES	CONTROL ROD ASSY	3E6722A00633	136	CONTROL ROD ASSY	3E6722A00633	MCR0900
191	CS-HGH	17-fev-14	1270:15	3400	0031/14	-	MAREP	NIL	RH BAGGAGE RAM DOOR GAS SPRING REPLACED	52	NO	GAS SPRING	A441A0500B19B060	-	GAS SPRING	A441A0500B19B060	-
192	CS-HGH	18-fev-14	1272:05	3404	0032/14	-	MAREP	NIL	CORRECTION OF ECS COMPRESSOR UPPER BELT FOUND INCO	21	NO	-	-	-	-	-	-
193	CS-HGH	21-fev-14	1275:30	3412	0033/14	-	MAREP	BLUE MAIN ROTOR DAMPER LEAKING	BLUE MAIN ROTOR DAMPER REPLACED	62	YES	MAIN ROTOR DAMPER	3G6220V01351	19188	MAIN ROTOR DAMPER	3G6220V01352	2272
194	CS-HGH	13-mar-14	1282:10	3427	0038/14	-	MAREP	DISPLAY UNIT #2 FAILING	DISPLAY UNIT #2 DU-1080-2 REPLACED	31	NO	DISPLAY UNIT	7037620-814	07125463	DISPLAY UNIT	7023460-804	06012713
195	CS-HGH	27-mar-14	1303:05	3479	0049/14	-	MAREP	NIL	LH LANDING LIGHT REPLACED	33	NO	LANDING LAMP	GE4596	-	LANDING LAMP	GE4596	-
196	CS-HGH	1-abr-14	1311:40	3507	0053/14	-	MAREP	NIL	RH POSITION LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
197	CS-HGH	5-mai-14	1358:40	3630	0079/14	-	MAREP	NIL	RH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
198	CS-HGH	13-jun-14	1424:50	3813	0109/14	-	PIREP	"2Y AP FAIL" APPEARS TWICE: FIRST IN LEFT TURN AND SECON	QRH A/C IS SERVICEABLE	22	NO	-	-	-	-	-	-
199	CS-HGH	16-jun-14	1425:40	3815	0110/14	-	MAREP	DISPLAY UNIT #3 WITH 3DU DEGRADE CAS MESSAGE. WORKS	DISPLAY UNIT #3 REPLACED	31	NO	DISPLAY UNIT	7023460-804	06123963	DISPLAY UNIT	7023460-804	06022721
200	CS-HGH	30-jun-14	1450:50	3892	0117/14	-	MAREP	NIL	LH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
201	CS-HGH	4-jul-14	1462:20	3927	0121/14	-	PIREP	ROTOR BRAKE FAIL IN FLIGHT	ROTOR BRAKE SYSTEM INSPECTED AND FUNCTIONED. NO FAU	63	NO	-	-	-	-	-	-
202	CS-HGH	4-jul-14	1463:20	3930	0122/14	-	MAREP	NIL	LINEAR ACTUATOR REPLACED	67	NO	LINEAR ACTUATOR	2-8486-3	1831	LINEAR ACTUATOR	2-8486-3	1954
203	CS-HGH	4-jul-14	1463:20	3930	0122/14	-	MAREP	BLUE TAIL ROTOR DAMPER WITH BEARING WEAR	BLUE TAIL ROTOR DAMPER REPLACED	64	YES	TAIL ROTOR DAMPER	3G6420V00455	LK1607	TAIL ROTOR DAMPER	3G6420V00455	LK1089
204	CS-HGH	8-jul-14	1470:55	3955	0125/14	-	MAREP	NIL	LINEAR ACTUATOR REPLACED	67	NO	LINEAR ACTUATOR	2-8486-3	669	LINEAR ACTUATOR	2-8486-3	1831
205	CS-HGH	17-jul-14	1485:05	4017	-	20140632	MAREP	2 BUSHES OF TAIL ROTOR SPIDER AND SLIDER ASSY: WORN O	BUSHES REPLACED	64	NO	SLEEVE BEARING	M81934/2-06C014	-	SLEEVE BEARING	M81934/2-06C014	-
206	CS-HGH	25-jul-14	1500:40	4052	0139/14	-	MAREP	NIL	LIGHTNING DIVERTER STRIPS REPLACED	52	NO	CABLE DIVERTER LIGHTNII	16795-10	-	CABLE DIVERTER LIGHTNII	16795-10	-
207	CS-HGH	4-ago-14	1508:15	4071	0145/14	-	PIREP	FUEL PROBE ON CAS WINDOW WITH READOUT "0" ON FUEL C	CHECKED THE CONNECTORS, TESTED ON GROUND, NO FAULT	28	NO	-	-	-	-	-	-
208	CS-HGH	5-ago-14	1508:15	4071	0146/14	-	PIREP	FUEL PROBE #1	FUEL PROBE #1 REPLACED	28	NO	SECONDARY PROBE	3G2840V01051	1106	SECONDARY PROBE	3G2840V01051	2781
209	CS-HGH	9-ago-14	1517:55	4114	0149/14	-	MAREP	ROD END ASSY: PLAY OUT OF LIMITS	ROD END (LAG DAMPER) REPLACED	62	YES	ROD END ASSY	M006-01H004-045	169RWW	ROD END ASSY	M006-01H004-045	MCR8746
210	CS-HGH	27-ago-14	1540:55	4186	0166/14	-	MAREP	NIL	LH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
211	CS-HGH	27-ago-14	1540:55	4186	0166/14	-	MAREP	NIL	RH POSITION LIGHT REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
212	CS-HGH	1-set-14	1545:30	4200	0170/14	-	MAREP	NIL	LAMP (SEARCH LIGHT) REPLACED	33	NO	SEARCH LAMP	4580	-	SEARCH LAMP	4580	-
213	CS-HGH	1-set-14	1545:30	4200	0170/14	-	MAREP	NIL	LH BAGGAGE BAY GAS SPRING REPLACED	52	NO	GAS SPRING	A441A0500B19B060	-	GAS SPRING	A441A0500B19B060	-



ANOMALIES AND RELIABILITY CONTROL BOOK

NO.	REGISTRY	OCCURENCE INFORMATION			DOCUMENTATION REFERENCE			ANOMALIES REPORTED	CORRECTIVE ACTION	COMPONENT		SYSTEM AND/OR COMPONENTS (OUT)			SYSTEM AND/OR COMPONENTS (IN)		
		DATE	FH	LDGS	TECH-LOG	WORK ORDER	TYPE			ATA	CRITICAL	DESCRIPTION	PART NUMBER	SERIAL NUMBER	DESCRIPTION	PART NUMBER	SERIAL NUMBER
214	CS-HGH	3-set-14	1549:55	4212	0172/14	-	MAREP	NIL	YELLOW TAIL ROTOR DAMPER LIGHTNING CONDUCTOR REPLACED	64	NO	LIGHTNING CONDUCTOR	A537A03AA03-0265	-	LIGHTNING CONDUCTOR	A537A03AA03-0265	-
215	CS-HGH	10-set-14	1556:05	4228	0177/14	-	PIREP	ENGINE #1 INOP DUE TO ITT READOUT FAILURE ENIGNE IN AN	AIRCRAFT ON GROUND	72	YES	-	-	-	-	-	-
216	CS-HGH	27-set-14	1556:05	4228	0178/14	20140827	PIREP	NIL	ENGINE #1 T5 TERMOCOUPLE HARNESS REPLACED	72	YES	THERMOCOUPLE HARNES	3073649-01	UNK	THERMOCOUPLE HARNES	3073649-01	EMA181600
217	CS-HGH	8-nov-14	1594:15	4337	0201/14	20140991	MAREP	LH STABILIZER WINGLET DAMAGED DUE TO IMPACT	LH STABILIZER WINGLET REPLACED	55	NO	LH WINGLET ASSY	3G5510A04831	A7/064	LH WINGLET ASSY	3G5510A04831	HS1
218	CS-HGH	12-nov-14	1594:15	4337	0203/14	-	MAREP	NIL	RH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
219	CS-HGH	12-nov-14	1594:15	4337	0203/14	-	MAREP	NIL	LH LANDING LAMP REPLACED	33	NO	LANDING LAMP	4596	-	LANDING LAMP	4596	-
220	CS-HGH	21-nov-14	1599:25	4350	-	20140976	MAREP	P2 DOOR HEELS BATTERY DISCHARGED	HEELS BATTERY REPLACED	33	NO	HEELS BATTERY PACK	8162-2	013261	HEELS BATTERY PACK	8162-2	013283
221	CS-HGH	21-nov-14	1599:25	4350	-	20140976	MAREP	P1 DOOR HEELS BATTERY DISCHARGED	HEELS BATTERY REPLACED	33	NO	HEELS BATTERY PACK	8162-2	013260	HEELS BATTERY PACK	8162-2	016787
222	CS-HGH	21-nov-14	1599:25	4350	-	20140976	MAREP	TGB FAIRING SUPPORT BROKEN	TGB FAIRING SUPPORT ASSY REPLACED	53	NO	FAIRING SUPPORT ASSY	3G5355A05031	-	FAIRING SUPPORT ASSY	3G5355A05031	-
223	CS-HGH	24-nov-14	1607:50	4372	0212/14	-	MAREP	NIL	RH BAGGAGE BAY GAS SPRING REPLACED	52	NO	GAS SPRING	A441A0500B19B060	-	GAS SPRING	A441A0500B19B060	-
224	CS-HGH	13-jan-15	1654:10	4502	-	20141137	MAREP	YELLOW MAIN ROTOR PITCH LINK UPPER BEARING WORN TO	UPPER ROD END ASSY REPLACED	62	YES	UPPER ROD END ASSY	3G6230A01133	MCR4952	UPPER ROD END ASSY	3G6230A01133	MCR4107
225	CS-HGH	3-jan-15	1642:05	4461	0002/15	20150074	PIREP	1-2 Y TRIM FAILURE DURING AP TEST: BROKEN WIRES IN CABL	WIRES IN CABLE LOOM REPAIRED; YAW COOL BEEP TRIM SWIT	67	NO	COOL YAW BEEP SWITCH	928-0551/01	-	COOL YAW BEEP SWITCH	928-0551/01	-
226	CS-HGH	9-jan-15	1645:25	4472	0003/15	-	MAREP	NIL	LH POSITION LIGHT LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
227	CS-HGH	10-jan-15	1647:25	4479	0004/15	-	MAREP	NIL	REAR TAIL POSITION LIGHT LAMP REPLACED	33	NO	TAIL POSITION LAMP	6363/12-2	-	TAIL POSITION LAMP	6363/12-2	-
228	CS-HGH	29-jan-15	1678:45	4577	0019/15	-	MAREP	NIL	RH POSITION LIGHT LAMP REPLACED	33	NO	POSITION LAMP	M6363/12-2	-	POSITION LAMP	M6363/12-2	-
229	CS-HGH	29-jan-15	1680:35	4582	0020/15	-	MAREP	CPI CONFIGURATION UNIT FAILURE	CPI CONFIGURATION UNIT REPLACED	25	NO	CPI CONFIGURATION UNI	503-40	338	CPI CONFIGURATION UNI	503-40	828
230	CS-HGH	4-fev-15	1690:25	4605	-	20150085	MAREP	CRACK FOUND ON BATTERY SUPPORT PANEL	BATTERY SUPPORT PANEL REPAIRED	53	NO	PANEL ASSY	3G5331A13931	-	PANEL ASSY	3G5331A13931	-
231	CS-HGH	4-fev-15	1690:25	4605	0024/15	-	MAREP	NIL	#2 HYDRAULIC FILTER REPLACED	29	NO	PCM FILTER ELEMENT	1865-36	-	PCM FILTER ELEMENT	1865-36	-
232	CS-HGH	16-fev-15	1706:25	4645	0032/15	20150210	MAREP	ROD END ASSY FOUND WITH MARKS MISALIGNED	ROD END ASSY REPLACED	62	YES	ROD END ASSY	M006-01H004-045	MCR2450	ROD END ASSY	M006-01H004-045	MCR8738
233	CS-HGH	27-mar-15	1728:55	4705	-	20150358	MAREP	HUMS REPORT	IGB FLANGE COUPLING REPLACED	65	YES	INPUT SLIDING ADAPTER	3T6521A05657	TBH6878	INPUT SLIDING ADAPTER	3T6521A05657	NRB5630
234	CS-HGH	25-abr-15	1768:30	4829	0058/15	-	PIREP	1P TRIM FAIL	AIOP #1 MODULE REPLACED	31	NO	AIOP MODULE	7029194-1901	06120734	AIOP MODULE	7029194-1901	08041112
235	CS-HGH	27-abr-15	1768:30	4829	0059/15	-	PIREP	1-2P TRIM FAIL DURING TEST	PITCH TRIM ACTUATOR REPLACED	22	NO	TRIM ACTUATOR ASSY	3G2220V00137	949	TRIM ACTUATOR ASSY	3G2220V00137	8292
236	CS-HGH	27-abr-15	1768:30	4829	0059/15	-	PIREP	1-2P TRIM FAIL DURING TEST	REMOVE AIOP #1 MODULE; INSTALL AIOP #1 MODULE	31	NO	AIOP MODULE	7029194-1901	08041112	AIOP MODULE	7029194-1901	08041112